

## 3809 FIELD INSPECTION FORM

DATE OF INSPECTION 7-6-90 TIME 9:45 CASE SERIAL NO. 47058-45NLOCATION: Township 21 S, Range 1 E, S.L.M.  
Section 15, Subdivision NW NW  
Section \_\_\_\_\_, Subdivision \_\_\_\_\_INSPECTOR Linda Jackson DISTRICT & RESOURCE AREA Richfield / Sevier RiverClaimant Name Richard Hilgard Hilgard Present During Inspection: Yes / (No)Operator Name same Present During Inspection: Yes / (No)Others at Inspection: M.K. Jackson, Richfield D.O. geologistIs the Operation Active? NoMSHA PERMIT NO. None Is Permit Current? \_\_\_\_\_DOE PERMIT NO. " Is Permit Current? \_\_\_\_\_DNR PERMIT NO. " Is Permit Current? \_\_\_\_\_COUNTY SANITATION PERMIT NO. " Is Permit Current? \_\_\_\_\_OTHER PERMITS: "

Indicate type of operations being conducted:

## EXPLORATION

- ☐ Claim staking
- ☐ Clearing of timber or other vegetation
- ☐ Drill pads
- ☐ Drill holes (Plugged? yes / no)
- ☐ Trenches
- ☒ Test Pits
- ☐ Bulk Sampling Sites
- ☐ Reopened Old Adits/Shfts  
(Gated? yes / No)
- ☐ New Adits/Shfts (Gated? Yes / No)
- ☐ Explosive Use or Storage
- ☒ New Roads Constructed
- ☒ Other (Describe on General Comments)  
abandoned equipment

## MILLING

- ☐ Milling or Processing Facilities
- ☐ Leaching Pad and/or Ponds
- ☐ Powerlines
- ☐ Hazardous Materials Present
- ☐ Fuel Tanks ( Above / Below Ground)  
Amount Stored \_\_\_\_\_ gallons or cf
- ☐ Is Site Lined? \_\_\_\_\_ Bermed? \_\_\_\_\_
- ☐ Additional Roads
- ☐ Other (Describe on General Comments)

## MINING

- ☐ Underground Mine (Gated? Yes / No)
- ☐ Mine Dumps
- ☐ Surface Mine
- ☐ Placer Mine
- ☐ Tailings Pond
- ☐ Ore Stockpile
- ☐ Overburden Stockpiles
- ☐ Waste Stockpiles
- ☐ Vehicle Yarding Area
- ☐ Adits/Shfts in Operation
- ☐ Explosives Use or Storage
- ☐ New Roads Constructed
- ☐ Hazardous Materials Stored or in Use.
- ☐ Other (Describe on General Comments)

## STRUCTURES

- ☐ Temporary Camp Trailers
- ☐ Buildings on Skids
- ☐ Structures or Bldgs. Affixed to Land
- ☐ Other Camp Facilities
- ☐ Sanitary Facilities
- ☐ Full Time Occupancy of Site
- ☐ Seasonal or Temporary Occupancy
- ☐ Occupancy Identified in Notice/Plan
- ☐ Other (Describe on General Comments)

ACCESS:

Is public access allowed through site (e.g., no gates)? yes

Describe how access is blocked: A fence has been put up by claimant near mine entrance. But there is no gate.

Describe the location of all new and existing access routes considered to be part of this project area and show their locations on the attached inspection map:

Roads shown on map accompanying notice.

Describe the specifications of the roads (length, width of roadbed, total disturbed width from top of cuts to toe of sidecast, type of surfacing, presence and frequency of berms, ditches, culverts, water bars, etc.): New road 550 ft long.

250 ft of road has inside cuts of > 3 ft. Road is approx 15 ft wide.

2 pits

Are any of the road cuts greater than 3 feet on the inside edge? Was this mentioned in the notice/plan? yes / no

Was topsoil saved and stockpiled? Yes / No / Not enough available

Describe all equipment found on site: Digger, mineral separator, miscellaneous

OPERATIONS:

Is the operation causing obvious erosion or other degradation? Abandoned, rusting equipment, Drainage may be blocked by berm

What type of mining equipment is present? Same as above

Are toxic or hazardous materials stored or used on site? Yes / No If yes, describe:

Does operator/claimant have DOE permit for HAZMAT use? Yes / No / Are the materials being stored/used in accordance with conditions of DOE permit? Yes / No (if no, document on Attachment for immediate notification of DOE). NA

Were weapons observed on site? Yes / No If yes, describe:

RECLAMATION:

Has reclamation work reported by operator/claimant been completed: Yes ☒ No

Tailings reshaped:	Yes <input checked="" type="radio"/> No	Streambeds reshaped:	Yes <input checked="" type="radio"/> No
Roads/Drill sites reshaped:	Yes <input checked="" type="radio"/> No	Topsoil respread:	Yes <input checked="" type="radio"/> No
Drill holes plugged:	Yes <input checked="" type="radio"/> No	Area reseeded:	Yes <input checked="" type="radio"/> No
Has seeding been Successful	Yes <input checked="" type="radio"/> No		

Describe Condition of Vegetation (e.g., % coverage of disturbed area): \_\_\_\_\_

Area any noxious weeds present on the project area? Yes ☒ Describe weeds and any measures taken by operator/claimant for control: \_\_\_\_\_

Is reclamation adequate to allow release of acreage? Yes ☒ No

If not, what additional work is needed? Total reclamation. Removal of trash & equipment. Fill in pits, recontour, reseed area.

Total Cumulative Surface Disturbance from Past and Present Operations:   /   Acres

Total Acreage Reported as Reclaimed, but not Acceptable for Deletion :   0   Acres

Total Acreage Reported as Reclaimed, and Accepted by BLM (not active):   0   Acres

~~Total Acreage Reported as Reclaimed, and Accepted by BLM (not active): \_\_\_\_\_ Acres~~

Total Active Acreage of Disturbance Under this Notice or Plan :   0   Acres

Describe any Corrective Actions that must Take Place Immediately (including onsite instructions to operator): \_\_\_\_\_

Were any obvious violations of other agency permits identified? Yes ☒ If yes, describe permit and nature of violation: \_\_\_\_\_

GENERAL INSPECTION OBSERVATIONS AND COMMENTS:

This site has been abandoned. A great deal of trash & mining equipment has been discarded. Two small pits have been left open, 4'x2'x2' & 4'x4'x4'. An oil spill 3'x10' remains. New road constructed at southern end of site, 530' long, 12-15' wide. 250' of road has inside cuts > 3 ft. Site needs to be cleaned of trash &

GENERAL INSPECTION OBSERVATIONS AND COMMENTS (cont'd):

equipment. Pits need filling in. Road, pit, settling  
pond need to be reconstructed & sealed. Oil spill  
needs to be cleaned up.

OTHER LAND USE OBSERVED:

Are there any landfills or dumps for garbage, refuse, or other materials on site?  
(Yes) / No If yes, describe: Cans, boards, plastic containers, glass, refrigerator

Is there any evidence of other public surface use or of potential trespass in the vicinity?:

<input type="checkbox"/> Livestock	<input type="checkbox"/> Mineral Material Removal
Type: _____ Number Present _____	<input type="checkbox"/> Agriculture Developments
<input type="checkbox"/> ORV Use (Type: _____)	<input type="checkbox"/> Timber Removal (Other than Mining Use)
<input type="checkbox"/> Recreation Use (Type: _____)	
<input type="checkbox"/> Other Use: _____	

HOW MUCH TIME WAS SPENT ON SITE FOR THE INSPECTION? 1 hr

Lois L. Jackson  
Signature of Inspector